

MS-AS Studs

adapters



Adapters to connect accelerometers to machine faces.

Mounting Studs provide a secure, permanent or semi-permanent point of connection

Part No.	Connection Point 1	Connection Point 2
MS-AS006	Quick Fit Female	1/4"-28 UNF Male
MS-AS009	M6 Female	M8 Male
MS-AS026	10-32 UNF Male	M6 Male
MS-AS028	Quick Fit Female 1/2" UNC	1/4"-28 UNF Male
MS-AS030	M8 x 1.25 Female	1/8"BSPT Male
MS-AS032	Quick Fit Female	M8 Male
MS-AS039	Quick Fit Female 1/2" UNC	10-32 UNF Male
MS-AS045	Quick Fit Female	M5 Female
MS-AS088	Quick Fit Female 9/16" UNC	M5 Female
MS-AS092	3/8" UNF Female	3/8" NPT Male
MS-AS103	1/4"-28 UNF Female	1/4" NPT Male
MS-AS107-M6	M6 Female	M6 Male
MS-AS111	M8 Female	M8 Female
MS-AS119	1/4"-28 UNF Female	1/4"-28UNF Male
MS-AS121	1/4"-28 UNF Female	3/8"-16 UNC Male



MS-AS Studs

side entry accelerometer bolts



For use with side entry accelerometers to provide a male thread.

Mounting Studs provide a secure, permanent or semi-permanent point of connection

Part No.	Connection Point 1	Connection Point 2	
MS-AS042-M6	Socket Cap	M6 Male	
MS-AS042-M8	Socket Cap	M8 Male	
MS-AS098	Socket Cap	M6 Male	
MS-AS109	Socket Cap	1/4"-28 UNF Male	
MS-AS114	Hexagonal Head	M6 Male	
MS-AS129	Hexagonal Head	1/4"-28 UNF Male	

MS-AS Studs

Conical Mounts



For use with motor with existing conical mount.

Mounting Studs provide a secure, permanent or semi-permanent point of connection

Part No.	Connection Point 1	Connection Point 2
----------	--------------------	--------------------

MS-AS031-1/4-M8	1/4"-28 UNF Female	M8 Male
-----------------	--------------------	---------

MS-AS031-M6-M6	M6 Female 1/4"-28	M6 Male
----------------	----------------------	---------

MS-AS031-M6-M8	M6 Female	M8 Male
----------------	-----------	---------

MS-AS031-M8-M8	M8 Female	M8 Male
----------------	-----------	---------



Fin Mounts



For use in the fins of an electric motor.

Mounting Studs provide a secure, permanent or semi-permanent point of connection

Part No.	Connection
----------	------------

MS-AS040-40	1/4"-28 UNF Female 40 mm x 7 mm
-------------	------------------------------------

MS-AS040-50	1/4"-28 UNF Female 50 mm x 7 mm
-------------	------------------------------------



MS-AS Studs

fin mounts

MS-AS105-1 ¼"-28 UNF Female 30 mm x 13 mm



MS-AS105-2 ¼"-28 UNF Female 50 mm x 13 mm



MS-AS105-3 ¼"-28 UNF Female 45 mm x 5 mm




MS-AS105-4 ¼"-28 UNF Female 25 mm x 5 mm



MS-AS Studs

glue face



Glue face studs are designed to provide a stronger glue surface to connect an accelerometer via.

Mounting Studs provide a secure, permanent or semi-permanent point of connection

Part No.	Connection Point 1	Connection Point 2	
MS-AS014	1/4"-28 UNF Male	Glue Face x Ø19mm	
MS-AS019-15	Magnet	Glue Face x Ø15mm	
MS-AS019-18	Magnet	Glue Face x Ø18mm	
MS-AS019-24	Magnet	Glue Face x Ø24mm	
MS-AS019-30	Magnet	Glue Face x Ø30mm	
MS-AS019-38	Magnet	Glue Face x Ø38mm	
MS-AS027-M6	M6 Female	Glue Face x 20mm AF	
MS-AS027-M8	M8 Female	Glue Face x 20mm AF	
MS-AS027-M8x1	M8 x 1 Female	Glue Face x 20mm AF	
MS-AS029	10-32 UNF Male	Glue Face x Ø19mm	
MS-AS036	M8 Male	Glue Face x 20.6mm AF	
MS-AS059-1/4	1/4"-28 UNF Female	Glue Face x Ø19mm	
MS-AS059-M6	M6 Female	Glue Face x Ø19mm	
MS-AS059-M8	M8 x 1.25 Female	Glue Face x Ø19mm	
MS-AS087	Magnet - Ø5mm Centre Hole	Glue Face x Ø19mm	

MS-AS Studs

mounting/grub screws



Screw studs for use to adapt a female thread into a male thread.

Mounting Studs provide a secure, permanent or semi-permanent point of connection

Part No.	Connection Point 1	Connection Point 2			
MS-AS008	1/4"-28 UNF Male	M8 Male			
MS-AS020	10-32 UNF 3/8" Male	10-32 UNF 3/8" Male			
MS-AS021	1/4"-28 UNF Male	M10 Male			
MS-AS022	1/4"-28 UNF 1/2" Male	1/4"-28 UNF 1/2" Male			
MS-AS023	1/4"-28 UNF Male	M8 Male			
MS-AS024	1/4"-28 UNF Male	M6 Male			
MS-AS025	1/4"-28 UNF Male	3/8"-24 UNF Male			
MS-AS043	1/4"-28 UNF Male	10-32 UNF Male			
MS-AS053	1/4"-28 UNF Male	M6 Male			
MS-AS066	1/4"-28 UNF Male	M6 Male			
MS-AS067	1/4"-28 UNF Male	M8 Male			
MS-AS068	1/4"-28 UNF Male	M10 Male			

MS-AS Studs

mounting/grub screws

Part No.	Connection Point 1	Connection Point 2			
MS-AS069	1/4"-28 UNF Male	1/4"-28 UNF Male			
MS-AS076	1/2"-28 UNF Male	M6 Male			
MS-AS081	1/4"-28 UNF Male	M12 Male			
MS-AS083	1/4"-28 UNF Male	M10 Male			
MS-AS084	1/4"-28 UNF Male	M5 Male			
MS-AS086	1/4"-28 UNF Male	M8 x 1 Male			
MS-AS090	1/4"-28 UNF Male	M10 x 1.25 Male			
MS-AS101	1/4"-28 UNF Male	1/2"-28 UNF Male			
MS-AS102	1/4"-28 UNF Male	1/2"-28 UNF Male			
MS-AS104	1/4"-28 UNF Male	M6 Male			
MS-AS110	1/4"-28 UNF Male	M10 x 1.25 Male			
MS-AS112	1/4"-28 UNF Male	M12 x 1.5 Male			
MS-AS115	1/4"-28 UNF Male	1/2" - 13 TPI UNC x 1" Male			
MS-AS122	1/4"-28 UNF Male	M10 x 1 Male			

MS-AS Studs

isolation



Provides a barrier to cut down on electrical interference.

Mounting Studs provide a secure, permanent or semi-permanent point of connection

Part No.	Connection Point 1	Connection Point 2	
MS-AS046-1	M6 x 1 Female	M6 x 1 Male	
MS-AS046-2	1/4"-28 UNF Female	1/4"-28 UNF Male	
MS-AS046-3	M8 x 1.25 Female	M8 x 1.25 Male	
MS-AS051-1/4	1/4"-28 UNF Male	1/4" - 28UNF Female Nylatron	
MS-AS051-M6	M6 x 1 Male	M6 x 1 Female Nylatron	
MS-AS051-M8	M8 x 1.25 Male	M8 x 1.25 Female Nylatron	
MS-AS051-M8X1.25	M8 x 1.00 Male	M8 x 1.25 Female Nylatron	
MS-AS051-M10	M10 x 1.5 Male	M10 x 1.5 Female Nylatron	
MS-AS051-M10X1.25	M10 x 1.25 x 10mm Male	M10 x 1.25 Female Nylatron	































MS-AS Studs

Quick Fit threads



For use with accelerometers with quick-fit threads.

Mounting Studs provide a secure, permanent or semi-permanent point of connection

Part No.	Connection Point 1	Connection Point 2			
MS-AS001	Quick Fit Male	Glue Face			
MS-AS002	Quick Fit Male	M8 Male			
MS-AS003	Quick Fit Male	M6 Male			
MS-AS004	Quick Fit Male	1/4"-28 UNF Male			
MS-AS007	Quick Fit Male	M10 Male			
MS-AS010	Quick Fit Male	M8 x 1.25 Female			
MS-AS011	Quick Fit Male	M6 x 1 Female			
MS-AS012	Quick Fit Male	1/4"-28 UNF Female			
MS-AS013	Quick Fit Male (9/16" UNC)	Glue Face			
MS-AS018	Quick Fit Male (1/2" UNC)	Glue Face			

MS-AS Studs

Quick Fit threads

Part No. Connection Point 1 Connection Point 2

MS-AS033 Quick Fit Male M8 x 1 Male



MS-AS034 Quick Fit Male (1/2" UNC) M6 x 1 Male



MS-AS037 Quick Fit Male (1/2" UNC) M8 x 1.25 Male



MS-AS041 Quick Fit Male 3/8" BSP



MS-AS049 Quick Fit Male 1/8" BSP



MS-AS064 Quick Fit Male M5 Male



MS-AS065 Quick Fit Male Glue face and M6 x 1 Female



MS-AS072 Quick Fit Male M8 x 8mm Male



MS-AS078 Quick Fit Male Glue Face in 316L Stainless Steel



MS-AS108 Quick Fit Male M12 Male



MS-AS120 Quick Fit Male 1/4"NPT Male

